

# 溫室氣體查驗證書

證書登記號碼 : CF 50414059 0001

查驗報告號碼 : 14078482 001

證書持有者 :  華新麗華股份有限公司台中不銹鋼廠  
43541 台中市梧棲區加工出口區經三路 57 號

查驗範圍 : 本次查驗包含:  
- 華新麗華股份有限公司台中不銹鋼廠: 43541 台中市梧棲區加工出口區經三路 57 號

已依照 ISO 14064-3:2006 之要求, 就 ISO 14064-1:2006 之條文內容進行查驗. 查驗的過程包含:

- 文件審查, 訪談, 現場查驗與重新計算

基於取得的資訊進行評估, 台灣德國萊因之查驗結論:

- 雙方同意本次溫室氣體查驗為"合理保證等級".
- 查驗的實質性要求為 5%, 全球暖化潛勢(GWP)依據 IPCC 2007 執行, 資料與資訊為歷史性資料.
- 基準年為: 2016
- 查驗年為: 2017
- 碳排放總量為 73532.359 噸/二氧化碳當量(tCO<sub>2</sub>e)
  - 直接排放為 35708.8755 噸/二氧化碳當量(tCO<sub>2</sub>e) (48.56%)
  - 能源間接排放為 37823.4830 噸/二氧化碳當量(tCO<sub>2</sub>e) (51.44%)
  - 其他間接排放為 0.0000 噸/二氧化碳當量(tCO<sub>2</sub>e) (0.00%)
  - 生質燃燒排放為 0.0000 噸/二氧化碳當量(tCO<sub>2</sub>e)


有效性 : 本證書僅對查驗年度進行查驗, 非對管理系統進行驗證



Validation and Verification  
VB007

證書生效期為 2018/08/06

臺灣德國萊因技術監護顧問股份有限公司  
臺灣 105 臺北市八德路四段 758 號 11 樓

  
Jason J. S. Wu

德國萊茵大中華區管理系統服務  
2018/08/06

This Verification Statement is based on the information made available to TÜV Rheinland Taiwan and the engagement conditions detailed above. Therefore, TÜV Rheinland Taiwan cannot guarantee the accuracy or correctness of this information. TÜV Rheinland Taiwan cannot be held liable by any party relying or acting upon this Verification Statement.